



## Property Remediation

### CLIENT:

Local Municipality

### ROLE:

Prime Contractor/WBE

### CONTRACT AMOUNT:

Low 6 figures

### DATE COMPLETED:

October, 2018

### PROJECT HIGHLIGHTS:

- *Coordination utility clearances, permits, inspections*
- *Complete UST removals – Three UST's*
- *Demolition of building and septic system*
- *Product removal, tank cleaning*
- *Recycled tanks & piping*
- *Excavated and disposed of Petroleum Contaminated Soils*
- *Imported, placed, and compacted backfill*
- *Teamed with Consultant to navigate ODSA grant and get NFA*



Buckeye Elm Contracting bid and won this project as a Woman Business Enterprise. Buckeye Elm teamed with a local consultant to meet the obligations of the contract, where a site NFA was the goal. The project was an ODSA Grant. Buckeye Elm demolished the existing house structure and concrete surfaces, removed three underground storage tanks, removed one septic tank, excavated, transported and disposed of Petroleum Contaminated Soils, and restored the site. This project was completed on-time and within budget. The NFA was obtained shortly after field service completion.

***Buckeye Elm exceeded the client's expectations by teaming with a consultant to handle all aspects of the remediation including the ODSA grant and NFA process.***



782 Hartford St. • Worthington, OH 43085  
**888.315.8663 • buckeye-elm.com**